



UNIVERSAL BELTING RESOURCE

"Working Through Distribution"

2 Paisley Park
 Carmichaels PA 15320
 800-928-9995
 customers@ubelting.com
 www.universalbelting.com

This sheet is a guideline only. Every press is a little different. We recommend that you do a test splice with your press before attempting the actual belt splice.

110400

U0/3ES WHITE RIB

Splice (options)	Pressure (psi)	Temperature		Press Time	Foil (position)	Foil (type)	Skive Length (inch)
		TOP	BOTTOM				
Lap Splice	30	160° C 320° F	160° C 320° F	2 minutes	Center	PU Foil	2.5"
Finger Splice - Water Cooled	20	160° C 320° F	160° C 320° F	2 minutes	Bottom	PU Foil	N/A
Finger Splice - Carbon Fiber High Speed Press	15	165° C 329° F	160° C 320° F	45 seconds	Bottom	PU Foil	N/A
Mechanical Lace		# 36 Series (Clipper)					
		# 1 (Alligator)					
Note: Silicone on Bottom/course TPFE Top							
Recommended Joining Procedure: Lap Splice							