



UNIVERSAL BELTING RESOURCE

"Working Through Distribution"

2 Paisley Park
 Carmichaels PA 15320
 800-928-9995
 customers@ubelting.com
 www.universalbelting.com

This sheet is a guideline only. Every press is a little different. We recommend that you do a test splice with your press before attempting the actual belt splice.

200500

2P80/04/04F S WT

Splice (options)	Pressure (psi)	Temperature		Press Time	Foil (position)	Foil (type)	Skive Length (inch)
		TOP	BOTTOM				
Finger over Finger Finger over Lap	22	175° C 347° F	175° C 347° F	4 minutes	Center	PVC	N/A
Finger Splice	22	175° C 347° F	175° C 347° F	4 minutes	Top	PVC	N/A
Lap Splice	22	175° C 347° F	175° C 347° F	4 minutes	Top	PVC	N/A
		# 36 (Clipper)					
Mechanical Lace		Staple # 1 (Alligator)					
Note: Profile pad on bottom to retain profile							
Recommended Joining Procedure: Lap Splice							

