



**UNIVERSAL BELTING RESOURCE**

"Working Through Distribution"

2 Industrial Park Road  
 Carmichaels PA 15320  
 800-928-9995  
 customers@ubelting.com  
 www.universalbelting.com

This sheet is a guideline only. Every press is a little different. We recommend that you do a test splice with your press before attempting the actual belt splice.

**320211**

**SI/2E-AS M Blue**

Splice (options)	Pressure (psi)	Temperature		Press Time	Foil (position)	Foil (type)	Skive Length (inch)
		TOP	BOTTOM				
Finger Splice - Water Cooled	20	165° C 329° F	165° C 329° F	1 Minute	Bottom 2 PCS	PU	N/A
Finger Splice - High Speed	20	165° C 329° F	165° C 329° F	2 Minutes	Bottom 2 PCS	PU	N/A
		UCM 36 SP (Clipper)					
Mechanical Lace		#00 (Alligator)					
<b>Notes: Matt release paper top / Teflon bottom</b>							
<b>Recommended Joining Procedures: Finger Splice</b>							

