



**UNIVERSAL BELTING RESOURCE**

"Working Through Distribution"

# 2 Paisley Park  
 Carmichaels PA 15320  
 800-928-9995  
 customers@ubelting.com  
 www.universalbelting.com

This sheet is a guideline only. Every press is a little different. We recommend that you do a test splice with your press before attempting the actual belt splice.

140205

0/2EC-0 PET/COTTON WHITE

Splice (options)	Pressure (psi)	Temperature		Press Time	Foil (position)	Foil (type)	Skive Length (inch)
		TOP	BOTTOM				
Finger over Finger - Water Cooled	25	170° C 338° F	170° C 338° F	2 minutes	N/A	No Foil	N/A
Lap Splice	25	170° C 338° F	170° C 338° F	2 minutes	N/A	No Foil	N/A
Finger Splice - Carbon Fiber High Speed	15	165° C 329° F	165° C 329° F	1 minutes	N/A	No Foil	N/A
Mechanical Lace	# 36 (Clipper)						
<b>Note:</b>							
<b>Recommended Joining Procedure: Finger over finger</b>							

