



**UNIVERSAL BELTING RESOURCE**

"Working Through Distribution"

# 2 Paisley Park  
 Carmichaels PA 15320  
 800-928-9995  
 customers@ubelting.com  
 www.universalbelting.com

This sheet is a guideline only. Every press is a little different. We recommend that you do a test splice with your press before attempting the actual belt splice.

**200700**

**2P100/0/0 WT**

Splice (options)	Pressure (psi)	Temperature		Press Time	Foil (position)	Foil (type)	Skive Length (inch)
		TOP	BOTTOM				
Finger over Finger Finger over Lap	22	173° C 343° F	173° C 343° F	2 minutes	Center	PVC	N/A
Finger Splice	22	173° C 343° F	173° C 343° F	2 minutes	Top	PVC	N/A
Lap Splice	22	173° C 343° F	173° C 343° F	1 minute	None	PVC	N/A
<b>Mechanical Lace</b>							
		# 36 (Clipper)					
		Staple # 1 (Alligator)					
<b>Note: One ply silicone on top/rough Teflon on bottom</b>							
<b>Recommended Joining Procedure: Finger over Lap</b>							

